

Railway Association Association des chemins de fer du Canada

99 Bank Street, Suite 901, Ottawa, ON Canada K1P 6B9 **T** 613 567 8591 **F** 613 567 6726 www.railcan.ca

99 rue Bank, bureau 901, Ottawa, ON Canada K1P 6B9 T 613 567 8591 **TÉLÉC** 613 567 6726 www.railcan.ca/fr

CIRCULAR NO. M-2

Centre-Beam Cable Condemning Limits and Replacement Procedures


Effective: March 30, 2011



99 rue Bank, bureau 901, Ottawa, ON Canada K1P 6B9 T 613 567 8591 TÉLÉC 613 567 6726 www.railcan.ca/fr

Every wire rope has three basic components:

- 1. The wires which form the strands and collectively provide rope strength;
- 2. The strands, which are helically around the core; and,
- 3. The core, which forms a foundation for the strands.



- 1. Any cable depicting one or more of the following defects should be replaced on sight:
 - a) Frayed cables with more than thirteen wires broken at any one location or one broken strand:



b) Broken cables:



Railway Association Association des chemins of Canada de fer du Canada 99 Bank Street, Suite 901, Ottawa, ON Canada K1P 6B9 T 613 567 8591 F 613 567 6726 www.railcan.ca

99 rue Bank, bureau 901, Ottawa, ON Canada K1P 6B9 **T** 613 567 8591 **TÉLÉC** 613 567 6726 www.railcan.ca/fr



c) Flattened cross-section (crush cable)/ Kinks greater than 60°



d) When knots cannot be removed and interfere with proper winding of cable (improperly wound cable)



Railway Association Association des chemins de fer du Canada

99 Bank Street, Suite 901, Ottawa, ON Canada K1P 6B9 **T** 613 567 8591 **F** 613 567 6726 www.railcan.ca

99 rue Bank, bureau 901, Ottawa, ON Canada K1P 6B9 T 613 567 8591 TÉLÉC 613 567 6726 www.railcan.ca/fr



Properly wound cable



- Cable chain is worn or corroded more than 25% e)
- If cable size is reduced by(0.4mm) 1/64 of an inch per each (8mm)¹/₄ inch f) diameter of cable (i.e. if a 1 in. cable is worn down more than 1/16 of an inch)
- If loose clamp bolts cannot be tightened, they must be replaced with a 3/16 clamp g)



99 rue Bank, bureau 901, Ottawa, ON Canada K1P 6B9 T 613 567 8591 TÉLÉC 613 567 6726 www.railcan.ca/fr

2. Cable replacement on centre-beam cars:

- a) Cable tail must not protrude more than 6 inches outside of ratchet barrel
- b) Bolted clamp must be properly fitted inside the ratchet barrel and tight against the hole on the barrel

Cable U-Bolt Clamp improperly installed (clamp too large)



Cable U-Bolt Clamp properly installed





99 rue Bank, bureau 901, Ottawa, ON Canada K1P 6B9 T 613 567 8591 TÉLÉC 613 567 6726 www.railcan.ca/fr



c) All cables must be properly tied down as per manufacturer recommendation before railcar is released.

The above applications are based on safe working procedures and are aimed at preventing incidents/accidents to employees while loading rail cars.