

Circular Letter

Subject: Correction to Office Manual Price Matrices Retroactive to July 1, 2015

Re: Members and Private Car Owners

File Number: CRB-Gen

After the issuance of July 1, 2015 Price Master, it was called to our attention that the pricing for certain wheelset Job Codes may be in error and should be reviewed. As a result of this request, the Car Repair Billing Committee performed a review of all wheelset Job Codes. This review confirmed pricing errors in Job Codes 3340, 3343, 3346, 3354, 3370, 3373, 3376 and 3379 for billing period July 1, 2015 through July 15, 2015. The error in these Job Codes has been corrected in the re-issued Price Master effective July 1, 2015.

Billing Parties are encouraged to correct the pricing on the affected job codes before submitting July billing to Data Exchange.

For all parties issuing incorrect bills during the specified time period for the affected Job codes, this is your authority to counter bill the billed party in accordance with AAR Office Manual Rule 112.D.2. Also, see Office manual Rule 112.E.6 for CBA time limitations.

For ease of rendering counter bills, charts for the July 1, 2015 to July 15, 2015 are provided below, which reflect the current and corrected prices for the affected Job codes, as well as the amount allowed for CBA.

We apologize for any inconvenience this may have caused.

Counter Billing Amounts													
Date	JULY 1, 2015 to July 31, 2015												
Job Codes	Responsibility	Condition	Material	Labor Fixed	Labor variable	Total	Corrected material price	Labor fixed	Labor Variable	Total	CBA Allowed	Cost Recovery	
3340	Owner, Defect Card	1	\$2,808.09		\$100.14	\$2,908.23	\$2,988.86		\$100.14	\$3,089.00	-\$180.77	Under	
3340	Owner, Defect Card	4	\$2,052.74		\$100.14	\$2,152.88	\$2,233.51		\$100.14	\$2,333.65	-\$180.77	Under	
3340	Owner, Defect Card	5	\$2,258.88		\$100.14	\$2,359.02	\$2,439.65		\$100.14	\$2,539.79	-\$180.77	Under	
3343	Owner, Defect Card	1	\$2,656.26		\$100.14	\$2,756.40	\$2,763.12		\$100.14	\$2,863.26	-\$106.86	Under	
3343	Owner, Defect Card	4	\$2,015.51		\$100.14	\$2,115.65	\$2,122.38		\$100.14	\$2,222.52	-\$106.87	Under	
3343	Owner, Defect Card	5	\$2,172.23		\$100.14	\$2,272.37	\$2,279.10		\$100.14	\$2,379.24	-\$106.87	Under	
3346	Owner, Defect Card	3	\$1,588.27		\$100.14	\$1,688.41	\$1,769.04		\$100.14	\$1,869.18	-\$180.77	Under	
3346	Owner, Defect Card	4	\$2,147.91		\$100.14	\$2,248.05	\$2,328.68		\$100.14	\$2,428.82	-\$180.77	Under	
3354	Owner, Defect Card	3	\$1,616.23		\$100.14	\$1,716.37	\$1,723.10		\$100.14	\$1,823.24	-\$106.87	Under	
3354	Owner, Defect Card	4	\$2,100.25		\$100.14	\$2,200.39	\$2,207.12		\$100.14	\$2,307.26	-\$106.87	Under	
3370	Owner, Defect Card	1	\$3,099.08		\$100.14	\$3,199.22	\$3,279.85		\$100.14	\$3,379.99	-\$180.77	Under	
3370	Owner, Defect Card	3	\$1,794.52		\$100.14	\$1,894.66	\$1,975.29		\$100.14	\$2,075.43	-\$180.77	Under	
3370	Owner, Defect Card	4	\$2,343.73		\$100.14	\$2,443.87	\$2,524.50		\$100.14	\$2,624.64	-\$180.77	Under	
3370	Owner, Defect Card	5	\$2,549.87		\$100.14	\$2,650.01	\$2,730.64		\$100.14	\$2,830.78	-\$180.77	Under	
3373	Owner, Defect Card	1	\$2,947.24		\$100.14	\$3,047.38	\$3,054.11		\$100.14	\$3,154.25	-\$106.87	Under	
3373	Owner, Defect Card	3	\$1,822.48		\$100.14	\$1,922.62	\$1,929.35		\$100.14	\$2,029.49	-\$106.87	Under	
3373	Owner, Defect Card	4	\$2,306.50		\$100.14	\$2,406.64	\$2,413.37		\$100.14	\$2,513.51	-\$106.87	Under	
3373	Owner, Defect Card	5	\$2,463.22		\$100.14	\$2,563.36	\$2,570.09		\$100.14	\$2,670.23	-\$106.87	Under	

3376	Owner, Defect Card	3	\$1,879.26		\$100.14	\$1,979.40	\$2,060.03		\$100.14	\$2,160.17	-\$180.77	Under
3376	Owner, Defect Card	4	\$2,438.90		\$100.14	\$2,539.04	\$2,619.67		\$100.14	\$2,719.81	-\$180.77	Under
3379	Owner, Defect Card	3	\$1,907.22		\$100.14	\$2,007.36	\$2,014.09		\$100.14	\$2,114.23	-\$106.87	Under
3379	Owner, Defect Card	4	\$2,391.24		\$100.14	\$2,491.38	\$2,498.11		\$100.14	\$2,598.25	-\$106.87	Under